

SERVICE BULLETIN 19092601


MODELS COVERED: 65PFL5704/F7, 65PFL5604/F7

DIGITAL MAIN PART NUMBERS COVERED:

AB78ZMMA-002  
AB78XMMA-001  
AB78WMMA-001  
ABD8QMMA-001  
ABD8LMMA-002  
ABD8CMMAR001  
ABD8BMMAR001  
ABD8RMMAR001



When replacing the Digital Main, the antenna cable must be removed from the defective board and installed on the new board.



Failure to move the cable will result in the lack of range for the microphone.

If the cable is missing order replacement cable WX1AB78ZW611.

MM092619