

[ Internal Use Only ] <<The information in this document should not be used for other purpose than Sony and/or Sony authorized dealers (ASC/ASD).>>

Sony Corporation

No. DPPJ17-010-TN

## Technical News

Issued : March 15, 2017

**Subject: Service Part Registration [Power Block (G Board),  
A-2184-763-A]**

[Applicable Model ]

Model / Destination	Serial Number	Number of Unit
VPL-VW300ES C1		
VPL-VW300ES SYQ		
VPL-VW315 J1		
VPL-VW320 SYQ		
VPL-VW328 C1		
VPL-VW350ES U8		
VPL-VW365 UC7		
VPL-VW500ES C1		
VPL-VW500ES J1		
VPL-VW500ES SYQ		
VPL-VW500ES U8		
VPL-VW515 J1		
VPL-VW520 SYQ		
VPL-VW528 C1		
VPL-VW535 J1		
VPL-VW550ES SYQ		
VPL-VW558 C1		
VPL-VW600ES U8		
VPL-VW665 UC7		
VPL-VW675ES UC7		

**[Description]**

The parts on the power block (G MOUNT) are changed and new power block is registered as the service part.

**[Applicable Serial No.]**

All serial numbers of the applicable model information are applicable.

**[Part Change Info.]**

G MOUNT : Old : A-2061-835-A => New : A-2184-763-A  
Old and New part are compatible.

When replacing the G Board, old parts can be used until running out of parts stock.